

Steelhead Recovery Ranking of Watersheds

Watershed
Carpinteria
Gaviota
Jalama
Atascadero*
Mission
San Jose*
Arroyo Hondo
Rincon
Corral
Dos Pueblos
Tajiguas
Montecito
Tecolote
Refugio
El Capitan
San Ysidro
Arroyo Paredon
Arroyo Burro
Santa Anita
Tecolotito*
Arroyo Quemado
Gato
Cojo
San Onofre

Total Habitat Quantity (miles)	Total Habitat Quantity Rank
16.07	4
23.05	1
21.18	2
16.36	3
9.26	6
11.14	5
1.89	23
7.42	7
6.94	9
4.81	14
5.28	13
4.17	15
4.08	17
5.72	11
5.62	12
3.25	20
4.14	16
7.21	8
2.58	21
6.76	10
2.28	22
3.80	18
3.72	19
0.82	24

Average Habitat Quality	Average Habitat Quality Rank
0.793	2
0.434	23
0.571	16
0.455	22
0.633	11
0.515	19
0.885	1
0.740	4
0.748	3
0.649	9
0.577	14
0.735	5
0.668	8
0.575	15
0.733	6
0.710	7
0.612	13
0.538	17
0.632	12
0.398	24
0.504	20
0.494	21
0.525	18
0.637	10

Total Habitat Score (A)	Total Habitat Score Rank
12.58	1
9.89	3
11.99	2
6.97	4
5.67	5
3.74	9
1.65	21
5.37	6
5.15	7
3.12	12
3.04	13
3.02	14
2.55	15
3.22	11
4.12	8
2.28	17
2.48	16
3.72	10
1.51	22
1.93	18
1.09	23
1.87	20
1.93	19
0.52	24

Salmonid Status (B)
1.0
1.0
0.7
1.0
1.0
1.0
1.0
0.9
0.7
0.9
0.9
0.9
0.9
0.7
0.5
0.9
0.8
0.5
0.9
0.9
0.7
0.4
0.7
0.4
0.3
0.6

Steelhead Recovery Score (AxB)	Steelhead Recovery Priority
12.58	1
9.89	2
8.39	3
6.97	4
5.67	5
3.74	6
1.65	7
4.83	8
3.61	9
2.81	10
2.74	11
2.72	12
2.30	13
2.25	14
2.06	15
2.05	16
1.98	17
1.86	18
1.36	19
0.77	20
0.76	21
0.75	22
0.58	23
0.31	24

*Sub-watersheds of the Goleta Slough Watershed